



## California State Fire Marshal **CODE INTERPRETATION**

Date Issued	November 29, 2017	Interpretation	17-002
Topic	Exiting thru an elevator lobby (other than I-2 or I-2.1)		
Code Section(s)	2016 CBC §1020.6 exception 2,3; §1016.2 (1)		
Requested by	Thomas M. Dusza, P.E. Jensen Hughes		
Date Received			

**Question 1:**

Is it the intent of 2016 CBC 1020.6 to allow the route to the second exit from a rated corridor through an elevator lobby for all occupancies (other than I-2 or I-2.1) based upon 2016 CBC 1020.6 Exception 2 and 1016.2 item 1?

**Yes.**

**Question 2:**

Do the elevator doors require an S label at the hoist way door when a rated corridor passes through the elevator lobby?

**No.**

However, the S rating must be achieved by one of the approved methods in CBC 3006.3.