



## California State Fire Marshal **CODE INTERPRETATION**

Date Issued	12-05-02	Interpretation #	02-058
Topic	Group R, Division 2.1.1 Facilities		
Code Section(s)	Sections 310.9 & 310.10.2, California Building Code (1998 ed)		
Requested by	Stephen Hart NASIP 1050 Eileen Way Sacramento, CA 95831-5812		

***1. Is an existing (April 1991) Residential Care Facility (R-2.1.1) that has had no change to either their license or to the building structure required to have smoke detectors in the bedrooms?***

No. There were no smoke detector requirements in sleeping rooms at the time this facility was licensed.

***2. Is at least one manual pull station also required?***

No. There were no pull station requirements for facilities housing six or less at the time this facility was licensed.